



MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

April 12, 2007



Mine Name: Sunset (Rainbows End)
Operator Name: Steven Delong

190 East 300 North Ivins, Utah 84738-0504

Inspector(s): Doug Jensen, Daron Haddock
Other Participants: Russell Schreiner (BLM)

Mine Status: Inactive

Permit number: S/053/032

Weather: Sunny, Cold, windy

Inspection Date: February 14, 2007

Time: 9:30 AM

Elements of Inspection Evaluated Comment Enfo

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds		\boxtimes	
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)	\boxtimes		
6.	Concurrent Reclamation		\boxtimes	
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
	Soils			
10.	Revegetation			
	Air Quality			
12.	Other			

Purpose of Inspection:

Inspected this site in conjunction with the BLM to determine what needed to be done to reclaim this site since it has been inactive for so long.

Inspection Summary:

This site has been inactive for a number of years. Permit fees have not been paid for this past year nor has a bond been posted.

We hiked into the site from the Quail Spring/Daggot Flat road since the road going into the site is not in drivable condition.

There were four-wheeler tracks going into the mine site, but other than that there had been no recent activity at the site. There is an open portal and a small dump. Equipment left on the site include, a portable generator, a fuel tank and a large aluminum bin.

Since the site has been in suspension for a number of years, it should probably be cleaned up and closed. The equipment should be hauled out and the portal sealed. The small dump could be pulled back and the pad area eliminated. The access road is primarily self-reclaimed. There are some areas that may need some regarding and seeding, but this probably depends on the amount of re-disturbance that would occur when accessing the site for reclamation. Photos of the area were taken.

Conclusions and Recommendations:

The BLM plans to close their notice and the Division should probably follow suit. This operation has been in suspension for a number of years and Operator has not paid the permit fee or

Inspection Date: February 14, 2007; Report Date: April 12, 2007

Page 2 of 2 S/053/032

posted a bond. Unless there is immediate justification provided for keeping this site open, it should be reclaimed and closed.

Inspector's Signature

Haddrek Date: 4/12/07

dh:pb

cc:

Steven Delong


Russ Schreiner, BLM, ST George FO (UTU-70057)

Attachment: Photos

 $P:\GROUPS\MINERALS\WP\M053-Washington\S0530032-Sunset\nspections\02142007 insp.doc$

ATTACHMENT

Photographs
S530032, Sunset, Steven Delong
Inspection Dated: February 14, 2007; Report Dated: April 13, 2007





ATTACHMENT

Photographs
S530032, Sunset, Steven Delong
Inspection Dated: February 14, 2007; Report Dated: April 13, 2007



